Beechcraft

SERVICE BULLETIN



MTB-57-01

TITLE

WINGS - INSPECT THE AFT UPPER AND LOWER WING BOLTS FOR CORRECT WASHER AND REPLACE IF NEEDED

EFFECTIVITY

SERIAL NUMBERS MODEL King Air 90 (applicable LJ-2055 thru LJ-2129 variants within defined LJ serial range) Super King Air 200/B200 BB-2019 thru BB-2021 Super King Air 200C/B200C BL-171 Super King Air B200GT BY-152 thru BY-261 Super King Air B200CGT BZ-1 Super King Air B300 FL-817 thru FL-1065 FM-53 thru FM-66 Super King Air B300C

REASON

To inspect the aft upper and lower wing bolts for incorrectly installed 95-110025-3 Washer, and if installed replace with a new 95-110025-7 Washer.

DESCRIPTION

This service document provides parts and instructions to remove the 95-110025-3 Washer installed on the aft upper and lower wing bolt and replace with a new 95-110025-7 Washer.

COMPLIANCE

RECOMMENDED. This service document should be accomplished at a scheduled maintenance period or inspection, not to exceed 200 flight hours.

A service document published by Textron Aviation may be recorded as completed in an aircraft log only when the following requirements are satisfied:

- The mechanic must complete all of the instructions in the service document, including the intent therein.
- 2) The mechanic must correctly use and install all applicable parts supplied with the service document kit. Only with written authorization from Textron Aviation can substitute parts or rebuilt parts be used to replace new parts.
- The mechanic or airplane owner must use the technical data in the service document only as approved and published.
- 4) The mechanic or airplane owner must apply the information in the service document only to aircraft serial numbers identified in the Effectivity section of the document.
- 5) The mechanic or airplane owner must use maintenance practices that are identified as acceptable standard practices in the aviation industry and governmental regulations.

March 5, 2020

MTB-57-01 Page 1 of 5

Textron Aviation Customer Service P.O. Box 7706, Wichita, KS 67277, U.S.A. 1-316-517-5800

This document contains technical data and is subject to U.S. export regulations. This information has been exported from the United States in accordance with export administration regulations. Diversion contrary to U.S.

COPYRIGHT © 2020

Boletin Serv.
MTR_57_01

Beechcraft

SERVICE BULLETIN



MTB-57-01

No individual or corporate organization other than Textron Aviation is authorized to make or apply any changes to a Textron Aviation-issued service document or flight manual supplement without prior written consent from Textron Aviation.

Textron Aviation is not responsible for the quality of maintenance performed to comply with this document, unless the maintenance is accomplished at a Textron Aviation-owned Service Center.

APPROVAL

Textron Aviation received FAA approval for the technical data in this publication that changes the airplane type design.

FLIGHT CREW OPERATIONS

None

CONSUMABLE MATERIAL

No specialized consumable materials are required to complete this service document.

TOOLING

No specialized tooling is required to complete this service document.

WEIGHT AND BALANCE INFORMATION

Negligible

REFERENCES

King Air Structural Inspection and Repair Manual.

PUBLICATIONS AFFECTED

Applicable King Air Illustrated Parts Catalog.

ACCOMPLISHMENT INSTRUCTIONS

- 1. Prepare the airplane for maintenance.
 - A. Make sure that the airplane is electrically grounded.
 - B. Make sure that all switches are in the OFF/NORM position.
 - C. Disconnect electrical power from the airplane.
 - (1) Disconnect external electrical power.
 - (2) Disconnect the airplane battery.
 - D. Attach maintenance warning tags to the battery and external power receptacle that have "DO NOT CONNECT ELECTRICAL POWER MAINTENANCE IN PROGRESS" written on them.
- (Refer to Figure 1, Sheet 1.) Examine the aft upper and lower wing bolls for the correct wing bolt washer as follows.
 - CAUTION: These inspections should be completed one attach-point at a time with the bolt installed and correctly torqued before moving to the next location. During removal the aft upper and lower wing bolts, make sure the wing is supported in a manner which will prevent the possibility of movement of the upper-attach fittings.
 - Remove the left upper and lower aft spar bolts.
 - B. Determine if a 95-110025-7 Washer is installed at the shown position on 81786-10-20 bolt.
 - (1) If a 95-110025-7 Washer is installed, no further action is required. Go to Step 3.
 - (2) If a 95-110025-7 Washer is not installed, go to Step 2.C.
 - C. Remove the 81786-10-20 Bolt and remove the 95-110025-3 Washer from the bolt.

MTB-57-01

Page 2

March 5, 2020

Boletin Serv. MTR-57-01


- D. Do the crack inspection of the wing structure (Flat surfaces, depressions and counterbores of the upper forward, upper and lower aff wing attack fittings). (Refer to King Air Series Structural Inspection and Repair Manual, Chapter 57, Crack Inspection - Wing Structure (LJ-1085, LJ-1088 and After (Table 201, Figure 201), Inspection - Wing Structure (BB-1158, BB1167, BB-1193 and After, BL-73 and After, BN-5 and After, BY-1 thru BY-121, BY-123 (Table 201, Figure 212, 213 and 214), and Crack Inspection - Wing Attach Fittings and Outboard Wing Spar Caps (Model B300.B300C) (Table 201, Figure 211, 212 and 213).
- E. Install a new 95-110025-7 Washer on the 81786-10-20 Bolt. (Refer to King Air Structural Inspection and Repair Manual, Chapter 57.)
- Install the left upper and lower aft spar bolts.
- Remove the maintenance warning tags and connect the airplane battery.
- Make an entry in the airplane logbook that states compliance and method of compliance with this service

NOTE: Textron Aviation recommends that compliance with all service documents is reported to a maintenance tracking system provider.

- Complete a record of compliance. (Maintenance Transaction Report, Log Book Entry, or
- other record of compliance.)
 Put a copy of the completed record of compliance in the airplane logbook.
 Send a copy of the completed record of compliance to the maintenance tracking system provider used.

MTB-57-01 Page 3

March 5, 2020



Boletin Serv. MTR_57_01

MATERIAL INFORMATION

Order the part below to install this modification.

NEW P/N	QUAN- TITY	KEY WORD	OLD P/N	IN D
95-110025-7	4	Washer		

^{*} Please contact Textron Aviation Parts Distribution for current cost and availability of part service document. Phone at 1-800-835-4000 (Domestic) or 1-316-517-5603 (International parts@txtav.com.

Based on availability and lead times, parts may require advanced scheduling.

Read free for 30 days. Read free for 30 days. On Walnut the Sullimentur Superior and past fronts. Instructions

Boletin Serv. MTR_57_01

TITLE

WINGS - CHECK FOR CORRECT WING BOLT WASHER AND REPLACE IF NEEDED

TO:

King Air 90 Series Aircraft Owner

King Air 200 Series Aircraft Owner

King Air 300 Series Aircraft Owner

REASON

To inspect the aft upper and lower wing bolts for incorrectly installed 95-110025-3 Wareplace with a new 95-110025-7 Washer.

COMPLIANCE

RECOMMENDED. This service document should be accomplished at a scheduled m inspection, not to exceed 200 flight hours.

LABOR HOURS

WORK PHASE	LABOR-HOUR
Modification	15.0
Inspection	1.0

MATERIAL AVAILABILITY

95-110025-7

PART NUMBER	AVAILABILITY	C

^{*} Please contact Textron Aviation Parts Distribution for current cost and availability of service document. Phone at 1-800-835-4000 (Domestic) or 1-316-517-5603 (Internato: parts@txtav.com.

Based on availability and lead times, parts may require advanced scheduling.

Boletin Serv. MTR-57-01

Eligibility: Airplanes identified within the serial number effectivity of this service docu

active Airframe warranty coverage on the original issue date of this docur

coverage must be active on the day the work is accomplished.

Textron Aviation-owned and Textron Aviation-authorized Service Facilities other maintenance facilities may submit a claim for the parts required to a

service document as defined in the *Material Availability* section of this do-

Labor Coverage: Textron Aviation-owned and Textron Aviation-authorized Service Facilities

maintenance on the specific model of Beechcraft Aircraft may submit a clinecessary to accomplish this service document as defined in the Labort

this document.

Credit Application:

Parts Coverage:

After this service document has been accomplished, a claim must be sub-Aviation within 30 days of the service document completion. Claims for conservice document are to be filed as a W4 type claim.

Please submit your claim form online at www.txtav.com/Parts or email the Textron Aviation Claim Form to warranty@txtav.com. If submitted on-line Authorization will be provided. If a paper claim is submitted your claim will the system and a Return Authorization will be sent to you.

The Return Authorization must accompany any required return parts (see Availability), to the point of purchase.

Parts to be returned to Textron Aviation Parts Distribution should be forwa

Textron Aviation Parts Distribution War ranty Administration 285 South Greenwich Road Bldg B89, Docks 1-4 Wichita, KS 67206 USA

Expiration: March 31, 2021

Textron Aviation reserves the right to void continued airplane warranty coverage for the parthis service document until the service document is accomplished.

NOTE: As a convenience, service documents are now available online to all our customer simple, free-of-charge registration process. If you would like to sign up, please visit Access link at www.txtevsupport.com to register.

Share this document

Gifts

Scribd for enterprise

About Support Legal Social Get our free apps **About Scribd** Help / FAO Terms @ Instagram App Store Press Accessibility Privacy **▼** Twitter Our blog Purchase help Copyright 6 Facebook Join our team! AdChoices Coolie Preferences Pinterest Contact us **Publishers** invite friends