



Aircraft Structural Inspections
Mr. Beau Hardison
Mr. Mark Welter
PO Box 2133
Mountain View AR 72560

2 September 2016

Gentlemen,

After review of the preliminary audit information and Mark Welter's previous training and certifications, Aircraft Structural Inspections Level II technicians are hereby authorized to perform NDT inspections that require a Level II in accordance with NAS-410. In addition, Mr. Welter is authorized to perform the following NDT inspections that require specific training and approval of Dassault Aviation:

- Embellisher RT - Falcon 20
- Wheel Well ET - Falcon 20
- Flap Rod UT - Falcon 20
- Spot Welds - Falcon 20
- Windshield Posts - Falcon 20/50
- Tail Attach Fittings - Falcon 10/20/50/900/2000
- Composites UT - Falcon 10/20/50/900/2000

These approvals are contingent on all of your technicians maintaining certification currency in accordance with NAS-410 and Dassault Falcon Jet's NDT Program Policies.

Feel free to contact me if you have any questions.

Welcome to the Falcon Family!

Regards,
Tim

A handwritten signature in cursive script that reads "Timothy Kinsella".

Tim Kinsella
Dassault Falcon Jet
NDT Program Manager
DFJ Completions Level III
Corporate Level III
201-417-0610